

Face/Head/Mouth
6

Eyes/Sight
2

Shoulder
0

Chest/Ribs
1

Back
10

Hip/Leg/Thigh
2

Knee
8



2017/2018

Hearing/Ear
6

Neck
1




Arm/Elbow
2

Abdomen/Side/Groin
0

Mental Health
0

Fingers/Hand/Thumb/Wrist
10

Ankle/Foot/Toes
6



Injury Summary

Serious Injury Potential;

- tractor and packer rollover
- contact with overhead powerline
- contact with underground line

Injury;

- pinned leg in ramp
- hit knee exiting vehicle
- dust in eyes
- while seated reached forward and hurt back
- wrench slipped hurt back

Other;


- threatening comments made during phone call
- speeding ticket issued
- chemical spill

P&E Summary

- CVA damage source unknown
- hit guard post at gas station
- tip over of sidearm
- drove over parking block
- during diagnostics damaged diesel fuel tank on oiler
- during sweeping damaged hitch bar
- contact with dead line between two poles
- drove into overhead door
- CVA left gravel road and hit ditch
- backed into private vehicle
- drove over creeper
- CVA rear-ended at intersection
- window damage due to flying objects x 3
- deer collision x 2
- battery/cables stolen from unit at stockpile

Safety Scorecard – Aug^{YTD} 2017

WCB Claims



Goal = 68 Claims^{Max}

YTD = 45 Claims
(8 out of 12 months)


Projection = 70 Claims

Status = **Action Needed**

Counter Measures

1. Identify barriers to safety prior to initiating task
2. Develop a safety first attitude.
3. Look out for yourself and others.

Lost Days



Goal = 795 Days^{Max}

YTD = 455 Days^{est}

Projection = 1090 Days
(5 out of 12 months)


Status = **Action Needed**

Counter Measures

When an injury results in medically supported time away from work case management must occur daily. The goal is to return our employees to work during the recovery period as soon as possible.

Accommodated work is available for all injury's.

P&E Incidents



Goal = 148 Incidents^{Max}

YTD = 63 Incidents
(5 out of 12 months)

Projection = 151 Incidents

Status = **Action Needed**

Counter Measures

1. Focus on backing up and contact incidents.
2. Complete a walk around your unit before moving.
3. Use a spotter as needed.
4. Ensure overhead doors are open.
5. Ensure box is down.
6. Ensure overhead line clearance is appropriate.
7. PM will reduce unplanned equipment failures.