









**Injury Rate Goal<sup>2016</sup> = TBD**

**Lost Days Goal<sup>2015/16</sup> = 1200<sup>Max</sup>**

**Property & Equipment Goal<sup>2015/16</sup> = 171<sup>Max</sup>**






### Snow Plow Incidents

**March** - Operator plowing Hwy 312 and a west bound vehicle hit wing.  
**March** - Operator plowing Hwy 11 when contacted by a semi.  
**January** - Operator was treating with salt with on Hwy 6; had stopped to let tow truck pull another semi out of the ditch; an oncoming semi lost control on the ice and struck the front of our plow truck.  
**January** - Employee plowing Hwy 11. Private vehicle in driving lane pulled out to pass traffic. Vehicle entered snow cloud. When private vehicle saw tandem they tried to avoid collision by driving into median and hit backside of left wing.  
**December** - None!  
**November** - Employee stopped unit on turning lane after salting intersection. A private vehicle approached from the rear, started to slide and hit the back left hand corner of the box. No injuries - damage to front of private vehicle.




### P&E Type

- Equip Failure = 26
- Equipment/Materials = 30
- Road = 17
- Building = 36
- MHI Unit = 20
- Private Vehicles = 12
- Other = 16
- Trailer = 5
- Light Standard/Post/Rail = 7
- Train Tracks = 2
- Bridge = 3
- Overhead Wires = 2



# Injury Rate Goal<sup>2016</sup> = TBD



# Lost Days Goal<sup>2015/16</sup> = 1200<sup>Max</sup>



# Property & Equipment Goal<sup>2015/16</sup> = 171<sup>Max</sup>



## Snow Plow Incidents

**March** - Operator plowing Hwy 312 and a west bound vehicle hit wing.

**March** - Operator plowing Hwy 11 when contacted by a semi.

**January** - Operator was treating with salt with on Hwy 6; had stopped to let tow truck pull another semi out of the ditch; an oncoming semi lost control on the ice and struck the front of our plow truck.

**January** - Employee plowing Hwy 11. Private vehicle in driving lane pulled out to pass traffic. Vehicle entered snow cloud. When private vehicle saw tandem they tried to avoid collision by driving into median and hit backside of left wing.

**December** - None!

**November** - Employee stopped unit on turning lane after salting intersection. A private vehicle approached from the rear, started to slide and hit the back left hand corner of the box. No injuries - damage to front of private vehicle.

## P&E Type

*Equip Failure = 26*  
*Equipment/Materials = 30*  
*Road = 17*  
*Building = 36*  
*MHI Unit = 20*  
*Private Vehicles = 12*  
*Other = 16*  
*Trailer = 5*  
*Light Standard/Post/Rail = 7*  
*Train Tracks = 2*  
*Bridge = 3*  
**Overhead Wires = 2**